





1/19



2/19




Figure 1E




Figure 1F

3/19

16 ↗

↙ 16




Figure 2A

Figure 2B




Fig. 2C

Fig. 2D

4/19

Fig. 3A




Fig. 3B





Fig. 3C



5119






figure 4

6/19



7/19




Fig 5B

8/19




Figure 6

9/19




Fig. 7




Figure 8A

52

11/19




Figure 8B





Figure 9B






Figure 10C

15119





FIG. 10D



Foot Stirrup
w/ Connecting Ring

Figure 11




FIG. 13A




FIG. 12




Figure 13B

19/19




Figure 14